



Photo 1 – FAA Photo of airplane on side of building inverted in parking area. Picture shows damage to the entire airframe.



Photo 2 – FAA photo of left wing on top of building structure buckled.