



Photo 1 – Photograph of airplane damage; airplane resting on hill. Note the sheared off nose landing gear in background. (Courtesy of FAA)



Photo 2 – Photograph of separated engine and propeller damage. (Courtesy of FAA)



Photo 3 – Left profile view of airplane resting on hill; separated nose gear in foreground. (Courtesy of FAA)