



Photo 1 – View of the airplane after it had been righted (Photo Courtesy of FAA)



Photo 2 – View of the airplane as it was being righted and a view of the landing area(Photo Courtesy of FAA)



Photo 3 – View of the cracked windscreen (Photo Courtesy of FAA)



Photo 3 – View of the cracked wing spar (Photo Courtesy of FAA)