



Investigative Photographs

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

ERA21LA061

December 20, 2020



Photograph 1¹ – Accident airplane – left side view.

¹ Photograph provided by Federal Aviation Administration.



Photograph 2² – Accident airplane – right side view.

² Photograph provided by Federal Aviation Administration.



Photograph 3³ – left wing damage.

³ Photograph provided by Federal Aviation Administration.



Photograph 4⁴ – left wing damage.

⁴ Photograph provided by Federal Aviation Administration.