



Photo 1 – Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Right Wing Damage (Photo Courtesy of FAA)



Photo 3 – Right Wing Aileron Damage (Photo Courtesy of FAA)



Photo 4 – Fuel Filter Screen Cover Gasket From Fuel Transfer Pump (Photo Courtesy of FAA)



Photo 5 – Unapproved Sight Gauge For Fuel Header Tank (Photo Courtesy of FAA)