



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA065



Photo 1 – View of airplane from left wing



Photo 2 – View of airplane from rear



Photo 3 – View of airplane from right wing



Photo 4 – View of runway markings (Photo Courtesy of Airplane Owner)



Photo 5 – View of runway markings leading to ground scars (Photo courtesy of airplane owner)



Photo 6 – Right main landing gear