



Photo 1 – View of the damage to the right wing leading edge and wing root. (Photo courtesy of the FAA)



Photo 2 – View of the closed taxiway and barricade that was struck. (Photo courtesy of the FAA)