



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA081



Photo 1 – Right Side View of Burned Wreckage and Downed Power Lines (Photo Courtesy of FAA)



Photo 2 – Left Side View of Burned Wreckage (Photo Courtesy of FAA)



Photo 3 – Closeup View of Burned Fuselage and Engine (Photo Courtesy of Tampa Police Department)



Photo 4 – View of Fuel Valve and Selector (Photo Courtesy of Piper Aircraft)



Photo 5 – View of Fuel Selector Valve with Selector Bezel Removed (Photo Courtesy of Piper Aircraft)



Photo 6 – Photo of Accident Airplane Interior in “For Sale” Advertisement (Photo from Internet)