



Photo 1 – Accident Site – Courtesy of NPD



Photo 2 – Main Wreckage Before Recovery – Courtesy of NPD



Photo 3 – Recovery of Main Wreckage – Courtesy of FAA



Photo 4 – Bottom of Left Wing – Courtesy of Piper Aircraft



Photo 5 – Propeller and Wing Roots – Courtesy of Piper Aircraft



Photo 6 – Bottom of Right Wing – Courtesy of Piper Aircraft



Photo 7 – Top of Right Wing – Courtesy of Piper Aircraft



Photo 8 – Right Aileron – Courtesy of Piper Aircraft



Photo 9 – Ferry Tank Fuel Selector – Courtesy of Piper Aircraft



Photo 10 – Damage to Mid and Aft Fuselage Areas – Courtesy of Piper Aircraft



Photo 11 – Close Up of Damage to Mid Fuselage Area – Courtesy of Piper Aircraft



Photo 12 – Close Up of Damage to Aft Fuselage Area – Courtesy of Piper Aircraft