



Photo 1 – FAA Digital Photograph. Frontal View of the Airplane Looking Aft. Note the Damage to the tip of Each Propeller Blade.



Photo 2 - FAA Digital Photograph. View Taken Aft of Nose Landing Gear Looking Forward and to the Right. Note The Structural damage to Bottom of Fuselage Aft of the Nose Landing Gear.



Photo 3 - FAA Digital Photograph. Close-Up View Taken Aft of Nose Landing Gear Looking Forward. Note Structural damage to Bottom of Fuselage Aft of the Nose Landing Gear.



Photo 4 - FAA Digital Photograph. View Taken Aft of Nose Landing Gear Looking Aft. Note the Structural Damage to the Bottom Portion of the Fuselage.



Photo 5 - FAA Digital Photograph. View Depicting Damage to the Firewall.