



Photo 1 – Overall view of right side of airplane wreckage. (Courtesy of FAA)



Photo 2 – Right aft view of airplane damage and concrete culvert in background. (Courtesy of FAA)



Photo 3 – View of damaged left-wing strut. (Courtesy of FAA)



Photo 4 – Close of view of fuselage damage. (Courtesy of FAA)



Photo 5 – View of damaged vertical stabilizer and rudder. (Courtesy of FAA)



Photo 6 – View of ground scars leading up to wreckage. (Courtesy of FAA)