



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA095



Photo 1 – View of Airplane from Right Rear (Photo Courtesy of FAA)



Photo 2 – View of Top of Airplane and Wing Roots (Photo Courtesy of FAA)



Photo 3 – View of Front of Airplane and Propeller (Photo Courtesy of FAA)



Photo 4 – View of Ground Scars and Airplane (Photo Courtesy of FAA)