



Photo 1 – airplane front view, wing tip, propeller damage, (FAA)



Photo 2 – right quartering view of rudder damage