



Photo 1 – Accident site, aircraft viewed from rear (courtesy of FAA)



Photo 2 - Accident site, aircraft viewed from left (courtesy of FAA)



Photo 3 – Closeup of aircraft propeller – note damage (courtesy of FAA)



Photo 4 - Closeup of aircraft engine – note damage (courtesy of FAA)



Photo 5 – Aircraft tail boom and empennage (courtesy of FAA)



Photo 6 – Closeup of tail boom damage (courtesy of FAA)