



Photo 1 – Left Side of Airplane at Accident Site (Courtesy of Groveland PD).



Photo 2 – Front Side of Airplane at Accident Site (Courtesy of Groveland PD).



Photo 3 – Left Side of Engine and Broken Drive Belt on Right (Courtesy of Groveland PD).



Photo 4 – Right Side of Engine and Broken Drive Belt on Left (Courtesy of Groveland PD).



Photo 5 – Broken End of Drive Belt (Courtesy of Groveland PD).