



Photo 1 – Main Wreckage (Photo Courtesy of FAA)



Photo 2 - Left Wing Leading Edge Ice (Photo Courtesy of FAA)



Photo 3 – Right Wing Leading Edge Ice (Photo Courtesy of FAA)



Photo 4 - Right Horizontal Stabilator (Photo Courtesy of Piper)



Photo 5 – Left Horizontal Stabilator (Photo Courtesy of Piper)