



Investigative Photographs

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

ERA21LA131

February 10, 2021



Photograph 1¹ – Accident airplane – Front left side view.

¹ Photograph provided by the accident pilot.



Photograph 2² – Accident airplane – Front right side view.



Photograph 3³ – Accident airplane – Aft right side view.

² Photograph provided by the accident pilot.

³ Photograph provided by the accident pilot.



Photograph 4⁴ – Accident airplane – Aft left side view.

⁴ Photograph provided by the accident pilot.



Photograph 5⁵ – Aft seat with cushion blocking control stick.

⁵ Photograph provided by the accident pilot.