



Airplane – View from Left (Photo Courtesy Unknown)



Airplane – View from Rear (Photo Courtesy Unknown)



Damage to Floor Structure Forward of Pressure Bulkhead (Photo Courtesy FAA)



Damage to Underside of Forward Fuselage (Photo Courtesy FAA)