



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA147



Photo 1 – View of Airplane from Right Wing (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Left Rear (Photo Courtesy of FAA)



Photo 3 – View of Empennage (Photo Courtesy of FAA)