



Photo 1 – View of post-fire damaged cockpit



Photo 2 – View of post-fire cockpit damage looking forward



Photo 3 – View of runway looking west with airplane skid marks starting at 1,200 before runway end (FAA photo)



Photo 4 – View of tire marks looking east of the end of the runway threshold into the grass