



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA161



Photo 1 – View of Airplane from Rear (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Left Wing (Photo Courtesy of FAA)



Photo 3 – View of Airplane from Right Wing (Photo Courtesy of FAA)



Photo 4 – View of Ground Scars (Photo Courtesy of FAA)



Photo 5 – View of PAPI and Charred Ground (Photo Courtesy of FAA)



Photo 6 – View of Runway 27 and Ground Scars (Photo Courtesy of FAA)