



Investigative Photographs

ERA21LA168

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

Photographs provided by the Federal Aviation Administration



Photograph 1 – Accident airplane – Front right view.



Photograph 2 – Accident airplane – Left side view.



Photograph 3 – Accident airplane – Right side view.



Photograph 4 – Accident airplane – Front view.



Photograph 5 – Accident airplane – Tail section view.