



Photo 1 – Left Side View of Main Wreckage – Courtesy of FAA



Photo 2 – Close Up of Left Side of Main Wreckage – Courtesy of FAA



Photo 3 – Right Landing Gear (Skid) – Courtesy of FAA



Photo 4 – Right Side View of Main Wreckage with Aft Portion of Tailboom in Foreground – Courtesy of FAA



Photo 5 – Close Up View of Right Side of Wreckage – Courtesy of FAA



Photo 6 – Rear View of Main Wreckage – Courtesy of FAA



Photo 7 – Tail Section – Courtesy of FAA



Photo 8 – Tail Rotor – Courtesy of FAA



Photo 9 – Pilot's Sandal – Courtesy of FAA



Photo 10 – Main Rotor Blade No. 1



Photo 11 – Main Rotor Blade No. 2



Photo 12 – Close Up of Break in Main Rotor Blade No. 2



Photo 13 – Aft Portion of Tailboom



Photo 14 – Tail Rotor Drive Shaft



Photo 15 – Broken Flexible Drive Shaft Coupling



Photo 16 - Main Rotor Head and Swash Plate



Photo 17 - Engine