



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA174



Photo 1 – Front view of airplane where it came to rest amongst.



Photo 2 – View of the left side of the airplane. (Photo courtesy of the FAA)



Photo 3 – View of the airplane from the rear. (Photo courtesy of the FAA)



Photo 4 – View of the accessory wall of the engine. (Photo courtesy of the FAA)