



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA175



Photo 1 – View of Airplane from Right Wing (Photo Courtesy of FAA)



Photo 2 – View of Airplane from Rear (Photo Courtesy of FAA)



Photo 3 – View of Airplane from Left Wing (Photo Courtesy of FAA)



Photo 4 – View of Airplane from Front (Photo Courtesy of FAA)



Photo 5 – View of Fuselage Damage (Photo Courtesy of Flight Safety Academy)



Photo 6 – View of Cabin Structural Frame Damage (Photo Courtesy of Flight Safety Academy)