



**Photo 1 – View of right side of airplane as it rests inverted off runway. Note damage to right wing. (Courtesy of FAA)**



**Photo 2 – View of front of airplane looking aft. Note crumpled left wing. (Courtesy of FAA)**



**Photo 3 – View of left side of airplane as it rests inverted. Note damaged vertical stabilizer. (Courtesy of FAA)**