



Photo 1 – FAA Digital Photograph. Left Side View of the Front Fuselage Depicting a Compression Wrinkle in the Lower Fuselage Aft of the Firewall.



Photo 2 - FAA Digital Photograph. Right Side View of the Airplane Depicting a Compression Wrinkle in the Lower Fuselage Aft of the Firewall.



Photo 3 - FAA Digital Photograph. View Depicting Buckling of the Pilot's Floor.