



Photo 1 – Tree Damage (FAA Photo)



Photo 2 - Main Wreckage Area (FAA Photo)



Photo 3 – Tailcone (FAA Photo)



Photo 4 – Main Rotor Hub (FAA Photo)



Photo 5 – Main Rotor (FAA Photo)



Photo 6 – Main Wreckage Area (FAA Photo)



Photo 7 – Engine (NTSB Photo)



Photo 8 – Engine and Cooling Scroll (NTSB Photo)



Photo 9 – Engine (NTSB Photo)



Photo 10 – Carburetor Floats and Fuel Screen (NTSB Photo)



Photo 11 – Carburetor Body (NTSB Photo)



Photo 12 – Spark Plugs (NTSB Photo)



Photo 13 – Landing Gear (NTSB Photo)



Photo 14 – Main Rotor Blades (NTSB Photo)



Photo 15 – Tail Rotor (NTSB Photo)