



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA192



Photo 1 – View of Airplane from Front Right (Photo Courtesy of FAA)



Photo 2 – View of Airplane Cockpit (Photo Courtesy of FAA)



Photo 3 – View of Airplane from Left Rear (Photo Courtesy of FAA)



Photo 4 – View of Fractured Tail (Photo Courtesy of FAA)



Photo 5 – View of Empennage in Tree (Photo Courtesy of FAA)



Photo 6 – View of Engine and Propeller (Photo Courtesy of FAA)



Photo 7 – View of Left Wing Section (Photo Courtesy of FAA)