



**Photo 1 – Front View of Main Wreckage – Courtesy of FAA**



**Photo 2 – Left Front View of Main Wreckage – Courtesy of FAA**



**Photo 3 – Left Side View of Main Wreckage – Courtesy of FAA**



**Photo 4 -Left Side View of Empennage – Courtesy of FAA**




**Photo 5 – Close Up of Empennage Courtesy of FAA**



**Photo 6 - Right Rear Side of Fuselage – Courtesy of FAA**



**Photo 7 – Throttle Cable and Standoff Clamp Under Load – Courtesy of FAA**



**Photo 8 - Throttle Cable and Standoff Clamp After Repositioning – Courtesy of FAA**