



Photo 1 – View of the airplane damage sustained to the forward fuselage and engine area (Photo Courtesy of FAA)



Photo 2 – View of the right-wing damage (Photo Courtesy of FAA)



Photo 3 – Overview of the damaged cowling and fuselage area (Photo Courtesy of FAA)