



Photo 1 – Main wreckage, hangar contact (FAA)



Photo 2 – Left wing view (FAA)



Photo 3 – Front view (FAA)



Photo 4 – right quartering tail view (FAA)