



Photo 1 – View of airplane after recovery. (Courtesy of FAA)




Photo 2 – View of Engine Mount Damage. (Courtesy of FAA)