



Photo 1 – Damage to Tree – Courtesy of FAA



Photo 2 – Scrap Marks from Rudder – Courtesy of FAA



Photo 3 – Ground Scars – Courtesy of FAA



Photo 4 – Damaged Truck – Courtesy of FAA



Photo 5 – Paint Transfer on Damaged Truck – Courtesy of FAA



Photo 6 – Main Wreckage – Courtesy of FAA



Photo 7 – Front View of Main Wreckage – Courtesy of FAA



Photo 8 – Right Side View of Main Wreckage – Courtesy of FAA



Photo 9 – Aft View of Main Wreckage – Courtesy of FAA



Photo 10 – Left Side View of Main Wreckage – Courtesy of FAA



Photo 11 – Propeller - Courtesy of FAA



Photo 12 – Scrape on Bottom of Rudder – Courtesy of FAA



Photo 13 – Nose Wheel Steering – Courtesy of FAA



Photo 14 –Left and Right Main Wheel Tracks – Courtesy of FAA



Photo 15 -Photos of Left and Right Main Wheel Tracks – Courtesy of WCSO



Photo 16 – Close Up of Tire tracks – Courtesy of WCSO