



Photo 1 – Digital Photograph from Operator. Right Side View of the Airplane at the Accident Site.




Photo 2 - Digital Photograph from Operator. Aerial View of the Airplane at the Accident Site.



Photo 3 – Digital Photograph From FAA. View Looking Aft of the Outer Portion of the Left Wing. Note the Damage to the Skin Across the Main Spar, and the Skin Buckling and Wrinkling.



Photo 4 - Digital Photograph From FAA. View Looking Forward of the Inboard Portion of the Right Wing. Note the Skin Buckling and Wrinkling at the Aft Spar Area.



Photo 5 - Digital Photograph From FAA. View of the Right Side of the Fuselage near the Right Aft Window and the Aft Window. Note the Skin Buckling and Wrinkling.