



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA227



Photo 1 – View of damage to right flap and gear door. (Photo courtesy of FAA)



Photo 2 – View of damage to VHF antenna. (Photo courtesy of FAA)