



**Photo 1 – View of inverted airplane adjacent to the structure it impacted. Note damage to wings and fuselage.
(Courtesy of FAA)**



Photo 2 – Forward view of airplane looking aft. Note leading edge damage to both wings. (Courtesy of FAA)



Photo 3 – Closeup view of airplane and structure damage. (Courtesy of FAA)



Photo 4 – View of airport approach light damage. (Courtesy of FAA)