



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA260



Photo 1 – View of airplane where it came to rest. (Photo Courtesy of FAA)



Photo 2 – View of engine. (Photo Courtesy of FAA)