



Photo 1 – View of the runway environment and airplane at the accident site (Photo Courtesy of Airport Authority)



Photo 2 – View of the airplane at the accident site (Photo Courtesy of Airport Authority)



Photo 3 – View of the airplane, note substantial damage to the fuselage and left wing (Photo Courtesy of Airport Authority)



Photo 4 – Closer view of the fuselage damage (Photo Courtesy of Airport Authority)