



ERA21LA270

Roscoe Hwy Rd

Small wire in (red) that helicopter impacted.

Large Transmission Tower

Larger transmission lines (gray) that pilot observed

Image Landsat / Copernicus

Google Earth