



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA277



Photo 1 – View of the left side of the airplane. (Photo Courtesy of FAA)



Photo 2 – View of grass blighting from the initial impact point to the wreckage. (Photo Courtesy of FAA)



Photo 3 – View of the right side of the wreckage. (Photo Courtesy of FAA)



Photo 4 – View of the fire damage to the engine and cockpit. (Photo Courtesy of FAA)