



Photo 1 – Main Wreckage (FAA Photo)



Photo 2 - Main Wreckage (FAA Photo)



Photo 3 – Right Wing Damage (FAA Photo)



Photo 4 – Fuel Tank Selector (NTSB Photo)



Photo 5 – Aft Fuselage (NTSB Photo)



Photo 6 – Forward Fuselage (NTSB Photo)




Photo 7 – Engine (NTSB Photo)



Photo 8 – Spark Plugs (NTSB Photo)




Photo 9 – Magnetos (NTSB Photos)



Photo 10 – Fuel Pumps (NTSB Photo)



Photo 11 – Fuel Filter (NTSB Photo)



Photo 12 – Suction Oil Filter Screen (NTSB Photo)