



Photo 1 – Accident Site (Photo Courtesy of FAA)



Photo 1 – Basket, Propane Tanks, And Burner



Photo 2 – Envelope As Found



Photo 3 – Envelope Examined



Photo 4 – Pilot Light Test