



Photo 1 – View of Airplane Facing Direction of Travel (FAA)



Photo 2 – View of Damage to Rudder/Vertical Stabilizer (FAA)



Photo 3 – View of Auto Fuel Drained from Gascolator (Right) and of Aviation Gasoline Used for Post-Accident Test Run (Precision Aviation)