



Photo 1 – Pilot's Footwell – Courtesy of FAA




Photo 2 – Copilot's Footwell – Courtesy of FAA



Photo 3 – Left Side of Forward Fuselage – Courtesy of FAA



Photo 4 – Left Lower Side of Forward Fuselage – Courtesy of FAA



Photo 5 – Bottom of Forward Fuselage – Courtesy of FAA



Photo 6 – Close Up Photograph of Buckling and Rivets (Bottom Forward Fuselage) – Courtesy of FAA



Photo 7 – Damage to 1st Propeller Blade – Courtesy of FAA



Photo 8 – Damage to 2nd Propeller Blade – Courtesy of FAA