




Investigative Photographs

ERA21LA302

Peter Wentz
Air Safety Investigator
Eastern Region Aviation



¹ – Accident airplane – Forward left side.



Photograph 2 – Accident Airplane – Damage to upper right wing

¹ Photographs provided by Federal Aviation Administration.