



Photo 1 – View showing weight-shift aircraft in tree line. Also showing structural damage to the airframe.



Photo 2 – View of weight-shift aircraft in tree line with fence post laying on the ground. Picture also shows structural damage to the right wing.