



Photo 1 – Digital Photograph Provided by FAA. Left Side View of the Airplane at the Accident Site.



Photo 2 – FAA Digital Photograph. View of the Firewall and Damaged Engine Mount.



Photo 3 - FAA Digital Photograph. View of the Left Fuel Gauge with Electrical Power Applied and No Fuel in Left Fuel Tank. Note the Needle Slightly Above Empty.



Photo 4 - FAA Digital Photograph. View of the Right Fuel Gauge with Electrical Power Applied and No Fuel in Right Fuel Tank. Note the Needle at Empty.