



Photo 1 – View of the helicopter and fire in engine compartment (twitter.com)



Photos 2 & 3 – View of the helicopter and fire shortly after impact (twitter.com)



Photo 4 – View of the helicopter at the accident site after fire extinguished (Photo Courtesy Beta Air LLC.)



Main Wreckage Final Resting Area



Broken tree branches

Photo 5 & 6 – View of the helicopter main wreckage location and tree impact (Photos courtesy of FAA)