



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA310



Photo 1 – View of Airplane from Right Wing (Photo Courtesy of Operator)



Photo 2 – View of Airplane Cockpit (Photo Courtesy of Operator)



Photo 3 – View of Airplane from Front (Photo Courtesy of Operator)